

GREG BELL Lieutenant Governor

# State of Utah

#### DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

epresentativ	es Present During the Inspection:
Company	Dave Shaver
OGM	Karl Houskeeper

## **Inspection Report**

Permit Number:	C0070019		
Inspection Type:	COMPLETE		
Inspection Date:	Monday, February 13, 2012		
Start Date/Time:	2/13/2012 9:30:00 AM		
End Date/Time:	2/13/2012 12:00:00 PM		
Last Inspection:	Monday, January 09, 2012		

Inspector: Karl Houskeeper. Weather: Cloudy, Temp. 33 Deg. F. InspectionID Report Number: 3010

> Accepted by: jhelfric 2/14/2012

Permitee: ANDALEX RESOURCES INC Operator: ANDALEX RESOURCES INC

Site: CENTENNIAL MINE

Address: PO BOX 910, EAST CARBON UT 84520-0910

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

**Current Acreages** 

6,516.91	Total Permitted			
47.19	Total Disturbed			
	Phase I			
	Phase II			
	Phase III			

Mineral Ownership

**Types of Operations ✓** Federal Underground **✓** State Surface County ☐ Loadout

**✓** Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Karl Houskeeper,

Inspector ID Number: 49

**Date** 

Monday, Febru



Permit Number: C0070019 Inspection Type: COMPLETE

Inspection Date: Monday, February 13, 2012

Page 2 of 3

## REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
  Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale	¥		~	
2.	Signs and Markers	<b>y</b>		~	
3.	Topsoil	V			
4.a	Hydrologic Balance: Diversions	Z			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	~		~	
4.c	Hydrologic Balance: Other Sediment Control Measures	~			
4.d	Hydrologic Balance: Water Monitoring	V			
4.ę	Hydrologic Balance: Effluent Limitations	Y	[]		
5.	Explosives	V	¥		
6.	Disposal of Excess Spoil, Fills, Benches	V	V		
7.	Coal Mine Waste, Refuse Piles, Impoundments	Y	<b>S</b>		
8.	Noncoal Waste	7	[]		[10.0]
9.	Protection of Fish, Wildlife and Related Environmental Issues	<b>Y</b>		· []	
10.	Slides and Other Damage	¥.			
11.	Contemporaneous Reclamation	Y			
12.	Backfilling And Grading	~			
13.	Revegetation	<b>y</b>		[]	
14.	Subsidence Control	V		e Politica de	
15.	Cessation of Operations	Y			
16.a	Roads: Construction, Maintenance, Surfacing	¥.		~	
16.b	Roads: Drainage Controls	V		[""]	
17.	Other Transportation Facilities	V			
18.	Support Facilities, Utility Installations	Ø		Sales des	
19.	AVS Check	<b>(</b>	[]		
20.	Air Quality Permit	V		<b>y</b>	
21.	Bonding and Insurance	<b>Y</b>			
22.	Other	~			

**inspection Continuation Sheet** 

Permit Number: C0070019 Inspection Type: COMPLETE

Inspection Date: Monday, February 13, 2012

Page 3 of 3

#### 1. Permits, Change, Transfer, Renewal, Sale

- The current DOGM permit was issued effective 01/04/2012 and expires on 01/04/2017.
- -Certificate of Insurance issued 06/01/2011 and terminates 06/01/2012.
- -Reclamation agreement dated and signed February 1990 (amended January 2001).
- -UPDES permit UT0025674 effective 12/01/2006 and expires midnight 11/30/2011.
- -Air Quality permit DAQE-997-96, issued October 25, 1996.
- -SPCC Plan dated 11/2/2009.

#### 2. Signs and Markers

The mine identification sign is in place at the entrance point into the mine permit area. The sign contains the required information.

## 4.b Hydrologic Balance: Sediment Ponds and Impoundments

The fourth quarter 2011 sediment pond inspections were reviewed during the complete inspection. No problems were noted for any of the sediment ponds...

### 16.a Roads: Construction, Maintenance, Surfacing

The erosional cut across the access road to the oil storage area has been fixed. Gravel has been placed inside of the cut and then been brought to grade.

#### 20. Air Quality Permit

The air quality permit DAQE-997-96 referenced above was issued on October 25, 1996 and remains in effect.